...fornia 94585

WETLANDS MAINTENANCE MANAGEMENT REPORT
SUISUN RESOURCE CONSERVATION DISTRICT

Date: 1-29-90

Club Name: Annie Mason Pt.

Ownership No. 801

Owner or Manager Jim TAYLOR

Acres in Ownership 51.5

Phone: (415) 758-209

*NOTE: YOU MUST SUBMIT A MAP OF YOUR PROPERTY SHOWING WORK LOCATIONS. SUITABLE MAPS ARE AVAILABLE FROM ASSESSOR'S OFFICE.

Type of Work	# of Units	Size or Acreage	Cubic Yards	Linear Feet	Work Schedule Start	Work Schedule Complete	Comments
Clearing Ditches	XXXXX	XXXXXXX	1,000	Approx. 1,200	As soon as possible	Oct. 1	1) upon Existing Levee
Construct New Ditches	XXXXXX						1)
Interior Levee Repair	XXXXXX	XXXXXXXX	2000	500'	"	"	2) From Existing Ditch
Exterior Levee Repair	XXXXXX	XXXXXXXX	2000	≈750'	"	"	2) Suisun Cut + Annie M Suisun Bay
Road Maintenance	XXXXXX	XXXXXXXX					2)
Grading Pond Bottoms	XXXXXX						
New Culverts			XXXXXXX	XXXXXXXX			
Repair-Replace Culverts			XXXXXXX	XXXXXXXX			
Water Control Structures			XXXXXXX	XXXXXXXX			3)
Install New Blinds		XXXXXXXX	XXXXXXX	XXXXXXXX			
Relocate Blinds		XXXXXXXX	XXXXXXX	XXXXXXXX			
Other Work (Specify)							

1) State where material will be placed 2) State source of material 3) State type of structure


N
GRIZZLY BAY
Exterior Levee Repair
INTERIOR Levee Repair
BUCKLER PT.
51.5 ACRES
INTERIOR Levee Repair
INTERIOR Levee Repair
INTERIOR Levee Repair
Exterior Levee Repair
Exterior Levee Repair
SUISUN CUT OFF
SIMMONS ISLAND
ANNIE
Exterior Levee Repair
MASON
SLOUGH